

1407 MONTANA AVE



**BUILDING AND STANDARDS BOARD AGENDA ITEM #6 FOR
WEDNESDAY, JANUARY 29, 2014**

**ENVIRONMENTAL SERVICES DEPARTMENT
CODE COMPLIANCE DIVISION**

MEMORANDUM
January 1, 2014

TO: The Honorable Chairman and Board Members

THROUGH: Elda Hefner Rodriguez, Division Manager, Code Compliance Department

FROM: Ron Roth, C.B.O., Deputy Building Official

SUBJECT: 1407 Montana Ave, El Paso, Texas, 799902-5617

The following is a brief chronology of the investigation of the referenced location:

- 1) First investigated on December 09, 2013. This multistory structure was built in 1908, constructed of brick with stucco finish and a wood framed roof structure. Attempts to maintain the structure secure have become unsuccessful. The structure was found accessible to vagrants. The structure consists of the shell and exposed wood and metal framing due to an abandoned construction project. The roof and ceiling assembly system is in disrepair throughout the structure. The remaining walls are full of graffiti. There are signs of settlement on the deck that is beginning to detach from the structure. There are trash and debris throughout the property.
- 2) A certified condemnation letter was mailed to John Lee.
- 3) Certified notices of the public hearing scheduled for January 29, 2014, were mailed to the owners and all interested parties on January 09, 2014.
- 4) As of January 06, 2014, \$2,509.27 is owed in taxes

The owner has been notified of the property violations at this property, to date there has been no response or corrective action taken, and therefore the Department recommends that it be found:

- 1) That the structure be condemned as substandard, and unfit for habitation or use and a hazard to the public health, safety, and welfare; and
- 2) That the structure is not in substantial compliance with the municipal ordinances regulating fire protection, structural integrity, and disposal of refuse; and
- 3) That the structure's certificate of occupancy be revoked; and
- 4) That the structure be registered as Vacant Building; and
- 5) That the structure can be rehabilitated; and
- 6) That the structure be secured and maintained secure within thirty (30) days; and
- 7) That the premises be cleaned and maintained clean of all trash, and debris within 30 days; and
- 8) That upon failure by the owner or any other interested party to comply with the order of the Building and Standards Commission the City may take whatever action is necessary to bring the property into compliance, and place a lien on the property for the work which will be done by the City.

Code Compliance Division
December 10, 2013
NOTICE OF VIOLATION

John Lee
1407 Montana Ave
El Paso, TX 79902-5617

Re: 1407 Montana Ave
Blk: 70/71 Franklin Heights
Lot: 7 & 8 & 42 & 43 (12900 Sq Ft)
Zoned: A-2
ENHS13-01103
9171999991703077389466

To All Owners, Lienholders, and Mortgagees:

An inspection at the above referenced address has revealed that the structure is in violation of the El Paso Municipal Code, Chapter 18.50, Property Maintenance Code, which states:

18.50.108.1 General.

When a structure or equipment is found by the Director to be unsafe, or when a structure is found unfit for human occupancy, or is found unlawful, such structure or equipment shall be condemned pursuant to the provisions of Title 2.38 of the Municipal Code.

The El Paso Municipal Code Chapter 18.50 International Property Maintenance Code defines unsafe structure as follows:

18.50.108.1.1 Unsafe Structures.

An unsafe structure is one that is found to be dangerous to the life, health, property or safety of the public or the occupants of the structure by not providing minimum safeguards to protect or warn occupants in the event of fire, or because such structure contains unsafe equipment or is so damaged, decayed, dilapidated, structurally unsafe or of such faulty construction or unstable foundation, that partial or complete collapse is possible

18.50.108.1.2 Unsafe Equipment

Unsafe equipment includes any boiler, heating equipment, elevator, moving stairway, electrical wiring or device, flammable liquid containers, or other equipment on the premises or within the structure that is in such disrepair or condition that such equipment is a hazard to life, health, property or safety of the public or occupants of the premises or structure.

18.50.108.1.3 Structure Unfit for Human Occupancy.

A structure is unfit for human occupancy whenever the Director finds that such structure is unsafe, unlawful or, because of the degree to which the structure is in disrepair or lacks maintenance, is unsanitary, vermin or rat infested, contains filth or contamination, or lacks ventilation, illumination, sanitary or heating facilities or other essential equipment required by

this code, or because the location of the structure constitutes a hazard to the occupants of the structure or to the public

The structure located at **1407 Montana Ave** is in violation of the requirements found in the following sections of the 2009 International Property Maintenance Code as adopted in the El Paso City Code, Chapter 18.50, Property Maintenance Code:

- a. All exterior property, accessory structures and premises shall be maintained in a clean, safe and sanitary condition, All accessory structures, including detached garages, fences and walls, shall be maintained structurally sound and in good repair. [Sec. 302.1, 302.2, 302.3, 302.4, 302.5, 302.6, 302.7, 302.8, 302.9]
- b. The exterior of a structure shall be maintained in good repair, structurally sound and sanitary so as not to pose a threat to the public health, safety or welfare. [Sec. 304.1, 304.1.1 conditions 1,2,3,4,5,6,7,8,9,10,11,12,13, 304.2, 304.3, 304.4, 304.5, 304.6, 304.7, 304.8, 304.9, 304.10, 304.11, 304.12, 304.13, 304.14, 304.15, 304.16, 304.17, 304.18]
- c. The interior of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 305.1, 305.2, 305.3, 305.4, 305.5, 305.6]
- d. The components of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 306.1, 306.1.1 conditions 1,2,3,4,5,6,]
- e. Every exterior and interior flight of stairs having more than four risers shall have a handrail on one side of the stair and every open portion of a stair, landing, balcony, porch, deck, ramp or other walking surface which is more than 30 inches (762 mm) above the floor or grade below shall have guards. [Sec. 307.1.1]
- f. All exterior property and premises, and the interior of every structure, shall be free from any accumulation of rubbish or garbage. [Sec. 308.1, 308.2, 308.2.1, 308.2.2, 308.3, 308.3.1, 308.3.2]
- g. All structures shall be kept free from insect and rodent infestation. All structures in which insects or rodents are found shall be promptly exterminated by approved processes that will not be injurious to human health. After pest elimination, proper precautions shall be taken to prevent reinfestation. [Sec.309.1, 309.2, 309.3, 309.4, 309.5]
- h. The building must comply with the minimum criteria and conditions for light. [Sec.402.1, 402.2, 402.3]
- i. The building must comply with the minimum criteria and conditions for ventilation. [Sec.403.1, 403.2, 403.3, 403.4, 403.5]
- j. The requirement for Privacy, minimum room dimensions, prohibited occupancy or food preparation spaces not met. [Sec.404.1, 404.2, 404.3, 404.4, 404.5, 404.6, 404.7]

- k. The building must comply with the minimum criteria of the provisions for required facilities. [Sec. 502.1, 502.2, 502.3, 502.4, 502.4.1, 502.5]
- l. The building must comply with the minimum criteria of the provisions for toilet rooms. [Sec. 503.1, 503.2, 503.3, 503.4]
- m. The building must comply with the minimum criteria of the provisions for plumbing systems and fixtures. [Sec. 504.1, 504.2, 504.3]
- n. The building must comply with the minimum criteria of the provisions for water systems. [Sec. 505.1, 505.2, 505.3, 505.4]
- o. The building must comply with the minimum criteria of the provisions for sanitary drainage systems. [Sec. 506.1, 506.2, 506.3]
- p. The building must comply with the minimum criteria of the provisions for heating facilities. [Sec. 602.2, 602.3, 602.4, 602.5]
- q. All mechanical equipment and fireplaces shall be properly installed and maintained. [Sec. 603.1, 603.2, 603.3, 603.4, 603.5, 603.6]
- r. The building must comply with the minimum criteria of the provisions for electrical facilities. [Sec. 604.1, 604.2, 604.3, 604.3.1, 604.3.1.1, 604.3.2, 604.3.2.1]
- s. All electrical equipment, wiring and appliances shall be properly installed and maintained in a safe and approved manner. [Sec. 605.1, 605.2, 605.3]
- t. Duct systems shall be maintained free of obstructions and shall be capable of performing the required function. [Sec. 607.1]
- u. Means of egress & Emergency escape opening - A safe, continuous and unobstructed path of travel has not been provided from all points in the building or structure to the public way. [Sec. 702.1, 702.2, 702.3, 702.4]
- v. The required fire-resistance rating of fire-resistance-rated walls, fire stops, shaft enclosures, partitions and floors shall be maintained. [Sec. 703.1, 703.2]
- w. All systems, devices and equipment to detect a fire, actuate an alarm, or suppress or control a fire or any combination thereof shall be maintained in an operable condition at all times. [Sec. 704.1, 704.1.1, 704.2, 704.3, 704.4]
- x. The structure needs to be secured from unwanted entry and ongoing vandalism, and the premises need to be cleaned of all trash and debris within (30) days from receipt of this letter. [Sec. 108.2]
- y. The repairs to the structural elements and/or service systems referred to in the previous sections must be completed within 30 days of your receipt of this letter. If, due to the scope and complexity of the work more time is needed, you must make this request to the Environmental Services Department, Code Compliance Division.

As a result of the aforementioned violations, the following action may be taken:

- a. This case is being submitted to the City Building and Standards Commission for unsafe structures proceedings. The Building and Standards Commission will decide if the structure is unsafe and if it should be vacated and secured, or demolished as per Title 2.38 of the El Paso Municipal Code.
- b. By authority of Chapter 18.02.103.10.3.3 of the El Paso Municipal Code the electrical service at this property may be disconnected at the request of the Environmental Services Department, Code Compliance Division because of Electrical Code violations.

Many of these corrections will require a permit. Permits for commercial or rental property must be taken out by a bonded and insured contractor who is registered with the City of El Paso.

According to the real property records of El Paso County, you own the real property described in this notice. If you no longer own the property, you must execute an affidavit stating that you no longer own the property and stating the name and last known address of the person who acquired the property from you. The affidavit must be delivered in person or by certified mail, return receipt requested, to the Code Compliance Division office, 7969 San Paulo Dr., El Paso, Texas, 79907, no later than the 20th day after the date you receive this notice. If you do not send the affidavit, it will be presumed that you own the property described in this notice, even if you do not.

Should you have any questions regarding this matter, please contact me at 599-6290.

Janeth Loya
Building Inspector

NOTICE OF PUBLIC HEARING

To all interested parties:

The owners, mortgagee, lien holders and any others with a legal interest in the property described below are hereby ordered to appear before the Building and Standards Commission, herein after referred to as the “Commission”, at the following time and place:

LOCATION: El Paso City Hall, City Council Chamber, 300 N. Campbell, 1st Floor, El Paso, Texas 79901

DATE: January 29, 2014

TIME: 5:30 p.m.

PROPERTY: 1407 MONTANA AVE, EL PASO, TEXAS also described as Lots 7, 8, 42 and 43, Block 70 (aka Blocks 70 and 71), SECOND SUPPLEMENTAL MAP OF FRANKLIN HEIGHTS ADDITION, an Addition to the City of El Paso, El Paso County, Texas, according to the map thereof recorded in Volume 9, Page 63, of the Plat Records of El Paso County, Texas.

The Property has been determined to be substandard based upon violations of the minimum standards of the 2009 Building Codes, adopted and incorporated in the El Paso City Code, Chapter 18, more specifically addressed below.

According to the real property records of El Paso County, and other relevant public records, John Lee, 1407 Montana Ave, El Paso, TX 79902-5617, is the owner, herein after referred to as the “Owner” of the Property. If you no longer own or have an interest in the Property, you must execute an affidavit stating that you no longer own or have an interest in the Property and stating the name and last known address of the person who acquired the property from you, if applicable. The affidavit must be delivered in person or by certified mail, return receipt requested, to Code Compliance Division of Environmental Services, 7969 San Paulo Drive, El Paso, Texas 79907, no later than the 20th day after the date you receive this notice. If you do not execute and deliver the affidavit, it will be presumed that you own or have an interest in the Property, even if you do not.

On or about December 9, 2013 an inspection of the Property was conducted by the Environmental Services Division and the following violations were identified:

- a. All exterior property, accessory structures and premises shall be maintained in a clean, safe and sanitary condition, All accessory structures, including detached garages, fences and walls, shall be maintained structurally sound and in good repair. [Sec. 302.1, 302.2, 302.3, 302.4, 302.5, 302.6, 302.7, 302.8, 302.9]
- b. The exterior of a structure shall be maintained in good repair, structurally sound and sanitary so as not to pose a threat to the public health, safety or welfare. [Sec. 304.1, 304.1.1 conditions

1,2,3,4,5,6,7,8,9,10,11,12,13, 304.2, 304.3, 304.4, 304.5, 304.6, 304.7, 304.8, 304.9, 304.10, 304.11, 304.12, 304.13, 304.14, 304.15, 304.16, 304.17, 304.18]

- c. The interior of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 305.1, 305.2, 305.3, 305.4, 305.5, 305.6]
- d. The components of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 306.1, 306.1.1 conditions 1,2,3,4,5,6,]
- e. Every exterior and interior flight of stairs having more than four risers shall have a handrail on one side of the stair and every open portion of a stair, landing, balcony, porch, deck, ramp or other walking surface which is more than 30 inches (762 mm) above the floor or grade below shall have guards.
[Sec. 307.1.1]
- f. All exterior property and premises, and the interior of every structure, shall be free from any accumulation of rubbish or garbage. [Sec. 308.1, 308.2, 308.2.1, 308.2.2, 308.3, 308.3.1, 308.3.2]
- g. All structures shall be kept free from insect and rodent infestation. All structures in which insects or rodents are found shall be promptly exterminated by approved processes that will not be injurious to human health. After pest elimination, proper precautions shall be taken to prevent reinfestation. [Sec.309.1, 309.2, 309.3, 309.4, 309.5]
- h. The building must comply with the minimum criteria and conditions for light. [Sec.402.1, 402.2, 402.3]
- i. The building must comply with the minimum criteria and conditions for ventilation. [Sec.403.1, 403.2, 403.3, 403.4, 403.5]
- j. The requirement for Privacy, minimum room dimensions, prohibited occupancy or food preparation spaces not met. [Sec.404.1, 404.2, 404.3, 404.4, 404.5, 404.6, 404.7]
- k. The building must comply with the minimum criteria of the provisions for required facilities. [Sec. 502.1, 502.2, 502.3, 502.4,502.4.1, 502.5]
- l. The building must comply with the minimum criteria of the provisions for toilet rooms. [Sec. 503.1, 503.2, 503.3, 503.4]
- m. The building must comply with the minimum criteria of the provisions for plumbing systems and fixtures. [Sec. 504.1, 504.2, 504.3]
- n. The building must comply with the minimum criteria of the provisions for water systems. [Sec. 505.1, 505.2, 505.3, 505.4]
- o. The building must comply with the minimum criteria of the provisions for sanitary drainage systems. [Sec.506.1, 506.2, 506.3]
- p. The building must comply with the minimum criteria of the provisions for heating facilities. [Sec. 602.2, 602.3, 602.4, 602.5]
- q. All mechanical equipment and fireplaces shall be properly installed and maintained. [Sec.603.1, 603.2, 603.3, 603.4, 603.5, 603.6]

- r. The building must comply with the minimum criteria of the provisions for electrical facilities. [Sec. 604.1, 604.2, 604.3, 604.3.1, 604.3.1.1, 604.3.2, 604.3.2.1]
- s. All electrical equipment, wiring and appliances shall be properly installed and maintained in a safe and approved manner. [Sec. 605.1, 605.2, 605.3]
- t. Duct systems shall be maintained free of obstructions and shall be capable of performing the required function. [Sec. 607.1]
- u. Means of egress & Emergency escape opening - A safe, continuous and unobstructed path of travel has not been provided from all points in the building or structure to the public way. [Sec. 702.1, 702.2, 702.3, 702.4]
- v. The required fire-resistance rating of fire-resistance-rated walls, fire stops, shaft enclosures, partitions and floors shall be maintained. [Sec. 703.1, 703.2]
- w. All systems, devices and equipment to detect a fire, actuate an alarm, or suppress or control a fire or any combination thereof shall be maintained in an operable condition at all times. [Sec. 704.1, 704.1.1, 704.2, 704.3, 704.4]
- x. The structure needs to be secured from unwanted entry and ongoing vandalism, and the premises need to be cleaned of all trash and debris within (30) days from receipt of this letter. [Sec. 108.2]
- y. The repairs to the structural elements and/or service systems referred to in the previous sections must be completed within 30 days of your receipt of this letter. If, due to the scope and complexity of the work more time is needed, you must make this request to the Environmental Services Department, Code Compliance Division.

The Owner is entitled to show cause that the Property is safe, does not constitute a dangerous structure and should not be declared a nuisance and ordered abated by presenting relevant evidence and testimony. If the Owner advocates for repair, then they bear the burden of proof to demonstrate the scope of any work that may be required to bring the property into compliance with Chapter 18.50 and the time it will take to reasonably perform the work. The allowable time periods for repair are governed by Texas Local Government Code, Sections 214.001(h), (i), (j) and (k). Any document relied upon to demonstrate that the Property is safe or that it can be repaired must be presented to the Commission at the hearing, including building plans, specifications, drawings, or reports from professionals and any other relevant documentation.

If the Owner fails to comply with the order of the Commission the City may pursue one or more of the following actions:

Perform any and all work necessary to bring the property into compliance with the Commission's order;

Assess civil penalties, provided for in the Commission's order, in an amount not to exceed \$1,000 per day or \$10 per day if the Property has a homestead exemption, that will accrue interest of 10% per year until paid in full;

Appoint a receiver as permitted by state law; and

Any other remedies permitted by state law.

Commission orders may be appealed to the State District Court within 30 days of the Final order.

The Commission's authority and procedures in regard to a Dangerous Structure Hearing may be found in Chapter 2.38 of the El Paso City Code and in their duly adopted bylaws. A copy of the ordinance adopting the most current version of Chapter 2.38 is enclosed. The bylaws may be obtained at the Code Compliance Division of Environmental Services, 7969 San Paulo Drive, El Paso, Texas 79907 or by calling (915) 599-6290.

This notice will be recorded in the real property records of El Paso County and will be binding on subsequent grantees, lien holders or other transferees of an interest in the Property.

The City Clerk is ordered to provide notice of this hearing to the record owners and all other interested parties, required by law, who are listed following this notice, and file this notice in the real property records of El Paso County.

FAILURE OF THE OWNER AND/OR LIENHOLDER OR MORTGAGEE TO TAKE THE ORDERED ACTION MAY RESULT IN THE CITY TAKING THE ORDERED ACTION AND FILING A LIEN AGAINST THE PROPERTY.

The City of El Paso appreciates your cooperation and prompt attention to remedying the nuisances on the Property. Please do not hesitate to contact me should you have any additional questions, comments or concerns relative to this notice.

APPROVED AS TO FORM

APPROVED AS TO CONTENT

John R. Batoon
Assistant City Attorney

Ron Roth, C.B.O.
Deputy Building Official

I, RICHARDA DUFFY MOMSEN, City Clerk of the City of El Paso, hereby certify that a true and correct copy of the foregoing Notice of Public Hearing regarding the property located at 1407 Montana Ave was filed with the County Clerk's Office, the official public records of real property for El Paso County.

Richarda Duffy Momsen

Executed this ____ day of _____, 2014 on behalf of the City of El Paso, Texas, by Richarda Duffy Momsen in her capacity as City Clerk.

STATE OF TEXAS
COUNTY OF EL PASO

Subscribed and sworn to before me, this ____ day of _____, 2014.

Notary Public

I, RICHARDA DUFFY MOMSEN, City Clerk of the City of El Paso, hereby certify that a true and correct copy of the foregoing Notice regarding the property located at 1407 Montana Ave, El Paso, Texas was PUBLISHED in the official City newspaper on the ____day of _____, 2014.

Richarda Duffy Momsen

I certify that a true and correct copy of the foregoing Notice regarding the property at 1407 Montana Ave was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

John Lee
1407 Montana Ave
El Paso, TX 79902-5617

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 1407 Montana Ave was HAND-DELIVERED to:

City of El Paso
C/O City Clerk
300 N. Campbell
El Paso, TX 79901

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 1407 Montana Ave was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Governor of the Ysleta Del Sur Pueblo Indian Tribe
AKA Tigua Indian Community
119 S. Old Pueblo Road
El Paso, Texas 79907

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 1407 Montana Ave was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

El Paso Central Appraisal District
5801 Trowbridge Ave.
El Paso, Texas 79925

Date: _____

Time: _____

Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 1407 Montana Ave was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

El Paso County Clerk, Probate Dept.
500 E. San Antonio Avenue, Suite 105
El Paso, Texas 79901

Date: _____

Time: _____

Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 1407 Montana Ave was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Delgado, Acosta, Spencer
Linebarger, Heard & Perez, LLP
Attn: Bonnie Cooper
221 N. Kansas Suite 1400
El Paso, TX 79901

Date: _____

Time: _____

Inspector: _____

I certify that a true and correct copy of the foregoing Notice was POSTED at 1407 Montana Ave, El Paso, Texas.

Date: _____

Time: _____

Inspector: _____



UNSAFE STRUCTURES REPORT

CODE COMPLIANCE DIVISION

DATE OF EXAMINATION: December 09, 2013

REP. DISTRICT: 8

ADDRESS: 1407 Montana Ave

ZONED: A-2

LEGAL DESCRIPTION: Lots 7, 8, 42 and 43, Block 70 (aka Blocks 70 and 71), SECOND SUPPLEMENTAL MAP OF FRANKLIN HEIGHTS ADDITION, an Addition to the City of El Paso, El Paso County, Texas, according to the map thereof recorded in Volume 9, Page 63, of the Plat Records of El Paso County, Texas.

OWNER: John Lee

ADDRESS: 1407 Montana Avenue
El Paso, TX 79902-5617

BUILDING USE: Abandoned multistory structure.

TYPE OF CONSTRUCTION: Type V, masonry and brick with stucco.

FOOTINGS: Concrete.

CONDITION: Unable to determine condition, footings are underground and must be evaluated by an engineer to determine actual condition.

FOUNDATION WALL: Combination masonry – rock with mortar grout.

CONDITION: Poor. Showing signs of deterioration due to lack of maintenance.

FLOOR STRUCTURE: Wood system covered with plywood.

CONDITION: Poor. The floor systems contain several holes and are deteriorated due to lack of maintenance. A structural engineer should be hired to evaluate the actual condition.

EXTERIOR WALLS: Combination brick - block covered by stucco and unfinished wood framed addition w/sheetrock covering.

HEIGHT: 25' +/-

THICKNESS: 10" +/-

CONDITION: Poor. Some structural deficiencies were found. The sheetrock on the unfinished addition contains many holes and is deteriorated due to exposure to the elements and vandalism. A structural engineer should be hired to evaluate structural elements of the building.

INTERIOR WALLS & CEILINGS: Metal framing and 2 x 4 wood studs covered with sheetrock and plaster in some areas.

CONDITION: Poor. Most of the wall coverings have been removed exposing the wood and metal framing. The few remaining walls are full of graffiti.

ROOF STRUCTURE: Wood framing covered w/composition shingles.

CONDITION: Poor. The roof system is deteriorated due to lack of maintenance and exposure to the elements. A licensed roofing contractor in the state of Texas should be hired to evaluate the roofing system.

DOORS, WINDOWS, ETC.: Wood frame and metal frame windows some w/wrought iron guards.

CONDITION: Poor. Several windows are broken due to vandalism.

MEANS OF EGRESS: No egress in the rear part of the building.

CONDITION: Poor.

PLUMBING: Poor. A licensed plumbing contractor must be hired to evaluate the entire plumbing system and submit a report to this department on the corrective action required to bring the system up to minimum code compliance.

ELECTRICAL: Poor. A licensed electrical contractor must be hired to evaluate the entire electrical system and submit a report to this department on the corrective action required to bring the system up to minimum code compliance.

MECHANICAL: Poor. A licensed mechanical contractor must be hired to evaluate the entire mechanical system and submit a report to this department on the corrective action required to bring the system up to minimum code compliance.

IF CONDEMNED, HOW MANY PERSONS WILL BE AFFECTED: None

WARNING POSTED: Yes **BARRICADED:** No **POLICE AID REQD.:** No

REMARKS: The open and abandoned multistory structure was built in 1908. Efforts to maintain the structure secure have become unsuccessful and entry by vagrants continues. The division recommends that the property be secured until repaired or demolished. That the property be cleaned of all trash and debris within thirty (30) days.

Janeth Loya
Building Inspector

TAX REPORT

Appraisal & Collection Technologies - EL PASO

Action Edit Query Record Field Help Entitlements Accounts Statements Window

ORACLE

Account Status

Prev. Acc... Next Acc... Prev. Owner Next Owner Acct History Acct Summary **Notes** Documents Go To:

EVAR
ACT8006 v1.242 01/06/2014 10:35
ACTEP

STATUS DETAIL Expand Fees Summary

Account Information

Account No. Roll Code

Certified Owner

Parcel Address

Amount Due as of CAD No.

Tax Units

Tax Unit Description

List of Tax Units

☐ AG INCLUDED ☐ Remove Fees ☐ Countywide ☐

Tax Unit, Yr, Rec. Type

Tax Unit

Year

Rec. Type

Multi Select

Amount Due/Paid Information

| Year | Gross Value | H | O | V | D | Base Levy | Paid Levy | Write-Off | Remaining Levy | Fees | Refund | Amount Due |
|---------------|-------------|---|---|---|---|--------------------|--------------------|---------------|-------------------|-------------------|---------------|-------------------|
| 2013 | \$93,446 | | | | | \$2,509.27 | \$0.00 | \$0.00 | \$2,509.27 | \$0.00 | \$0.00 | \$2,509.27 |
| 2012 | \$93,446 | | | | | \$2,437.75 | \$2,437.75 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 2011 | \$92,634 | | | | | \$2,373.66 | \$2,373.66 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 2010 | \$92,634 | Y | 2 | | | Excodes \$1,927.62 | \$1,927.62 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 2009 | \$102,439 | Y | 2 | | | Excodes \$2,131.44 | \$2,131.44 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 2008 | \$108,609 | Y | 2 | | | Excodes \$2,292.48 | \$2,292.48 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 2007 | \$108,609 | Y | 2 | | | Excodes \$2,314.95 | \$2,314.95 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 2006 | \$100,641 | Y | 2 | | | Excodes \$2,447.61 | \$2,447.61 | \$0.00 | \$0.00 | \$331.09 | \$0.00 | \$0.00 |
| 2005 | \$105,113 | | | | | \$3,282.07 | \$3,282.07 | \$0.00 | \$0.00 | \$1,432.31 | \$0.00 | \$0.00 |
| Totals | | | | | | \$44,902.47 | \$42,393.20 | \$0.00 | \$2,509.27 | \$1,983.01 | \$0.00 | \$2,509.27 |

Last Payment Date

Last Payer

Alert

9:35 AM
1/6/2014